


MANUAL BRUSH LIFTER
MOVE 90° CCW TO LIFT BRUSHES

ENCODER SOLDER TERMINALS
(POWER SUPPLY REQUIRED
+5 V TO +25 V, 50 mA)





SLIPRING SOLDER
TERMINALS (STATOR)

SLIPRING SOLDER
TERMINALS (ROTOR)

#8-32 CLEARANCE HOLES
TYP 4 PLACES
EQUALLY SPACE
ON A Ø2.250 BOLT CIRCLE

2.180 DIA.

1.250 DIA.



2.4990 +/- .0005 DIA

LOCATION OF ROTOR TERMINALS ON
OTHER SIDE OF FLANGE. NOT ACTUALLY
VISIBLE FROM EITHER END VIEW.